


STATE OF UTAH
DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS AND MINING
355 West North Temple
3 Triad Center, Suite 350
Salt Lake City, Utah 84180-1203
Telephone: (801) 538-5340
Fax: (801) 359-3940



ANNUAL REPORT OF MINING OPERATIONS

The informational requirements of this form are based on provisions of the Mined Land Reclamation Act, Title 40-8, Utah Code Annotated 1953, as amended, and the General Rules as promulgated under the Utah Minerals Regulatory Program. An operator conducting mining operations under a Notice of Intention must file an annual operations and progress report (FORM MR-AR) with the Division.

I. General Information

1. Report Time Period: From (mo./yr.) Jan. 1, 1995 to (mo./yr.) Dec. 31, 1995
 2. DOGM File Number (Mine No): M / 027 / 006 ML 35572 (Lease No.)
 3. Mine Name: Continental Lime Inc. - Cricket Mountain Plant
 4. Mineral(s) Mined (or permitted to mine): Building Stone / Limestone
 5. Type of mine ☒ Surface Mine or ☐ Underground Mine
 6. Legal Description (Location of Lands Affected):
NW 1/4, 1/4, Section 36, Township 21S, Range 10W
NW 1/4, 1/4, Section 2, Township 22S, Range 10W
1/4, 1/4, Section , Township , Range
 7. Name of Operator or Company: Continental Lime Inc.
 8. Permanent Street Address : 670 East 3900 South, Suite 205
City, State, Zip: Salt Lake City, UT 84107
Phone: (801) 264-6870
 9. Company Representative (or designated operator):
Name: Glen A. Bryant
Title: Vice President & General Manager
Business Address: 670 East 3900 South, Suite 205
City, State, Zip: Salt Lake City, UT 84107
Phone: 264-6865
- ☐ Please check if any of the above information has changed since previous year.

II. Mining and Reclamation

1. Was the mine active during the past year? Yes ☒ No ☐
2. If active, how much ore or mineral was mined? 1,406,000 tons

3. How much additional acreage was disturbed during the past year? 3 acres
4. Briefly describe any new or additional surface disturbances that occurred during the past year. This description should include the type of work performed, and volume of material moved.
Additional area was covered by the west waste dump. This new
area held approximately 350,000 tons of waste material.
5. How much acreage was reclaimed during the past year? 0
6. Briefly describe the reclamation work performed during the past year. This description should include methods employed, and an evaluation of the results.
The west slope catch-benches at the 5940, 5920 and 5900 elevations
were capped and covered with fines or growth media in preparation
for seed application.
7. What is the total disturbed acreage at years end? 112
8. Briefly summarize any mining and/or reclamation plans for the upcoming year.
Mining will continue from the 5900 elevation down to the 5840
level in 1996. The areas prepared for seeding in 1995 will be
seeded during early 1996 and other catch-benches will be reclaimed
in the fall of 1996.

NOTE: Section III., "Additional Information" applies only to large mining operations.

III. Additional Information

1. An updated surface facilities map should be attached if there have been significant changes since the previous map was submitted.
2. Any monitoring results or other reports that are required under the terms of the approved notice of intention should also be attached.

IV. Signature Requirement

I hereby certify that the foregoing is true and correct.

Name (Typed or Print):

Glen A. Bryant

Title of Operator:

Vice President & General Manager

Signature of Operator:



Date:

January 22, 1996